

ERSON CAMS 7301 GLOBAL DR LOUISVILLE, KY 40258

Part No.	E 119826	
Grind:	RH-276-4	
	114+6	Lobe Separation Angle
Overlap:	<u>51.00</u>	
Intake Opens:	<u>30.00</u>	Exhaust Closes: <u>21.00</u>
Intake Closes:	<u>66.00</u>	Exhaust Opens: <u>81.00</u>
Running Clearance:	<u>0.000</u>	<u>0.000</u> [Hot]
Valve Lift (Int / Exh):	<u>0.480</u>	<u>0.480</u>
Duration (Int / Exh):	<u>276</u>	<u>282</u>

Checking Figures @ .050" Tappet Rise

Overlap:	<u>-17.00</u>	
Intake Opens:	<u>-4.00</u>	Exhaust Closes: <u>-13.00</u>
Intake Closes:	<u>32.00</u>	Exhaust Opens: <u>47.00</u>
Duration Intake:	<u>208.0</u>	Duration Exhaust: <u>214.0</u>
Lobe Lift Intake:	<u>0.320</u>	Lobe Lift Exhaust: <u>0.320</u>
Intake Center Line:	<u>108</u>	
Rocker Arm Ratio:	<u>1.50</u>	

CAM NO.	SPECIAL NOTES
XXXXX	CATALOG

PART NO:E915055

SPRING # D A T E

CHECK HT

PRESSURE

CHECK HT

PRESSURE

RATE

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16